


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner

At the position described above, I set a 2 1/2" x 30" iron pipe 28" in the ground with a brass cap, marked as shown.

From which I scribed BTs:

- A fir 14" S 13°20' E 42.0' scribed NW 1/16 S 3 BT.
- A fir 15" N 31°40' W 17.4' scribed NW 1/16 S 3 BT.

I nailed a brass washer marked OPLS 1097 to BT blazes.


I set a steel fence post 5' North and 5' East with signs 54-4 and 54-2.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T16 and measured a horizontal distance to the center of the BTs.

This corner was set August 19, 1980. Witness by Patrick L. Murphy.

See map of survey.



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James H. Buisman

OREGON
JULY 22, 1977
JAMES H. BUISMAN
1097

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the day of.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

To Received _____

Date Filed _____

GPO 796-333

By _____

File No. 17-84 R