


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner

At the position described above, I set a 2 1/2" x 30" iron pipe 26" in the ground with a brass cap marked as shown.

From which I scribed BTs:

A spruce 11" in diam. bears S 15°27' E 142.9' scribed CN 1/16 S3 BT.

A fir 19" in diam. bears N 45°24' W 146.9' scribed CN 1/16 S3 BT.

I nailed a brass washer marked OPLS 1097 to BT blazes.


I set a steel fence post 5' West and 5' South with signs 54-2 and 54-4.

I painted a red band around BTs and face of scribe.

I used a steel tape and Wild T16 and measured a horizontal distance to the center of the BTs.

This corner was set August 20, 1980. Witness by Patrick L. Murphy.

See map of survey.



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*James H. Buisman*

OREGON  
JULY 22, 1977  
JAMES H. BUISMAN  
1097

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the ..... day of .....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

GPO 796-333

By \_\_\_\_\_

File No. 18-84 R