


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-2

History of original corner establishment:
None



Description of corner evidence found:
None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set from survey by Single proportionate measurement along E-W centerline of Section 6

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 25" in the ground, with brass cap attached, marked:

T1N R38E

W $\frac{1}{16}$ c ——— c S6

From which we mark new BT's:

A 14" Spruce, scribed "CW 1/16 S6 BT" on a double blaze bears N 74 1/2°W 8.2 ft.

PLS1099
1980

And a 12" Douglas Fir, scribed "CW 1/16 S6 BT" on a double blaze bears S45°W 25.0 ft.

Attached brass washer, marked "LS1099" to lower blaze of each BT.

Placed steel fencepost 5 ft. S of monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, 1979.

Compass Declination: 18° East

I hereby certify that the above described corner monument and/or accessories was established on Oct. 7, 1980.

Witness: John Curtiss

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1009

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by.....
(COUNTY OFFICIAL)

UNION COUNTY
SURVEYOR
(DEPUTY)

Received _____

Date Filed _____

By _____

File No. 20-84 R