


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-4

History of original corner establishment:

None



Description of corner evidence found:


None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set from survey by subdivision of section.

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 25" in the ground, approx. 30 ft. west of Dry Creek and approx. 150 ft. west of U.S.F.S. Rd. 3200, with brass cap attached, marked:

From which new BT's:



An 18" Larch, scribed "CE 1/16 S 6 BT" on a double blaze, bears N80°E 75.7 ft.,

A 16" Spruce scribed "CE 1/16 S6 BT" on a double blaze, bears S27°E 64.4 ft.

Attached brass washer, marked "LS1099" to lower blaze of new BT's.

Placed steel fencepost approx. 5 ft. North of monument with signs 54.2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey U.S.F.S. Region 6, Oct. 1979.

I hereby certify that the above described corner and/or accessories was established on Oct. 7, 1980.

Compass Declination: 18° East

Witness: John Curtiss

Office of..... County Surveyor County of..... Union
 State of..... Oregon I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL)

REGISTERED PROFESSIONAL LAND SURVEYOR

Gary L. Langlitz

OREGON
 JULY 22, 1977
GARY L. LANGLITZ
 1099

UNION COUNTY SURVEYOR
 (DEPUTY)

Received _____

Date Filed _____

By _____

File No. 21-84 R

☆ GPO—798-276