


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner

At the position described above, I set a 2½" x 30" iron pipe 21' in the ground with a Brass Cap, marked as shown, from which I scribe BT's.

Fir 18" N 71°40' W, 6.60 ft., scribed C¼ S 3 BT


Fir 11" S 11°33' E, 5.00 ft., scribed C¼ S 3 BT

I nailed a brass washer marked OPLS 1097 to BT blazers. I set a steel fence post 5 ft. North and 5 ft. East, with signs 54-4 & 2 and 54-4.

I painted a red band around BT's and face of scribe.

I used a steel tape and WILD T16 and measured a horizontal distance to the center of the BT's.

This corner was set 8/19/80, witness by Patric Murphy. See map of survey.



REGISTERED PROFESSIONAL LAND SURVEYOR

James H. Buisman

OREGON
JULY 22, 1977
JAMES H. BUISMAN
1097

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the day of

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Received _____

Date Filed _____

By _____ GPO 796-333

File No. 25-84 R