
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

#### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously Established.

#### T1N R38 EC-24



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

CORNER:

See Survey 015-2020

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS

At position determined by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

### NEW BEARING OBJECTS:

A 5" Douglas Fir bears North 32° West a dist. of 21.90 ft., marked CE 1/16 S1 BT. A 5" Douglas Fir bears South 71° West a dist. of 7.75 ft., marked CE 1/16 S1 BT.

Set fence post approx. 1 ft. North

I hereby certify that the corner was monumented on May 8, 2020. Witness: Kyle A. Tucker

REGISTERED **PROFESSIONAL** LAND SURVEYOR ØREGON JEFFREY S. HSU

83571 Renewal Date: June 30, 2021

GRIFFITH N X W X B T1N R38E E 1/16 -C  $C \cdot$ **S1 OPLS 83571** 2020

I used a steel tape and magnetic compass in the establishment of the new accessories. I used  $14^{\circ}$ East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY **SURVEYOR**