


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-9

History of original corner establishment:

Corner not previously established.




Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner.

At the position described above, I set a 2½" x 30" iron pipe 26" in the ground with a Brass Cap, marked as shown, from which I scribe BT's.
 Fir 12" dia. bears N 74°47' W, 17.70 ft. marked S1/16 S 5 BT
 Fir 7" dia. bears S 53°01' E, 22.40 ft. marked S1/16 S 4 BT
 I nailed a brass washer marked OPLS 1097 to BT blazers.
 I set a steel fence post 5 ft. East and 5 ft. South, with signs 54-4, 54-2 and 54-2.
 I painted a red band around BT's and face of scribe.
 I used a steel tape and WILD T16 and measured a horizontal distance to the center of the BT's.
 This corner was set 8/18/80, witness by Patrick Murphy.
 See map of survey.



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James H. Buisman

**OREGON
JULY 22, 1977
JAMES H. BUISMAN
1097**

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the day of ..
 by
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Received _____
 Date Filed _____
 By _____ GPO 796-333
 File No. 29-84 R