
### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously Established.

#### T1N R38 ED-24



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey 015-2020

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position determined by survey I set a  $5/8" \times 15"$  iron pin, 13" drilled into rock, with 2 1/2" aluminum cap marked as shown below, from which:

#### NEW BEARING OBJECTS:

A 2'x2'x2' rock outcrop bears South 82°44' East a dist. of 2.12 ft., marked X BO. A 5/8"x30" iron pin bears North 42°36' West a dist. of 17.16 ft., with 1 1/2" aluminum cap marked BGB Survey Marker.

Set fence post approx. 5 ft. South

I hereby certify that the corner was monumented on May 8, 2020.

Witness: Kyle A. Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU

83571 Renewal Date: June 30, 2021 SE 1/16 S1

OPLS 83571
2020

I used a Leica GS18 in the establishment of the new accessories. Basis of Bearing is as per Survey 015-2020. The distances and bearings are to the center of the X or to the center of the aluminum cap.