


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-4

History of original corner establishment:

None



Description of corner evidence found:

A steel fencepost bears S58°E 23.0 ft. from the monument described below. See Record Survey 23 -1964, Union County Surveyor's Office.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set from survey by single proportionate measurement.

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 25" in the ground, with brass cap attached marked:

T1N R38E

From which we mark new BT's:

An 8" Spruce scribed "E 1/16 S6 BT" on a double blaze bears N 8 1/2°E 25.6 ft.

And a 6" White Fir, scribed "E 1/16 S7 BT" on a double blaze bears S75°E 44.3 ft.

Attached brass washer, marked "LS 1099" on lower blaze of each BT.

Placed steel fenceposts 5 ft. N and E of monument with signs 54-2 and 54-9 attached to northerly post and sign 54-2 only to easterly post.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey U.S.F.S. Region 6, Oct., 1979.

S6 1/16  
E  
S7  
PLS1099  
1980

I hereby certify that the above described corner monument and/or accessories was established on Oct. 6, 1980.

Compass Declination: 18° East

Witness: John Curtiss

Office of..... County Surveyor..... County of..... Union.....  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by.....  
(COUNTY OFFICIAL)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gary L. Langlitz*  
OREGON  
JULY 22, 1977  
GARY L. LANGLITZ  
1099

**UNION COUNTY SURVEYOR**

Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 34 - 84 R

☆ GPO—798-276