CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original survey by contract and dated Aug. 29, 1891 The original notes read; Set post from which.; A spruce 7" in diam bears N61°w 26 lks. marked T1N R38ES5ET;

A spruce 7" in diam bears No.1" 26 lks. marked Tin R38ES5ET; A tamarack, 18" in diam bears S62°W 25 lks. marked Tin R38ES8ET

A fir 14" in diam bears S23°E 23 lks. marked TlN R38ES9BT; A fir 6" in diam bears N81°E 23 lks marked TlN R38Es4BT;

E-9			
DIAGRAM COR			
TIN	R38EWM		
S5 S8	S4 S9		

Description of corner evidence found:

A tamarack snag bears S62°W 25 lks with scribe; A stump bears S23°E 231 lks with scribe;

, ,	MON COUNTY SURVEYOR
' .fa	Received
to	Filed
8y	
File N	10. 38-84R

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2" pipe 30" long with brass cap on top from which the following new bearing trees were placed.

A Tamarack 5" in diam bears N9°W 28' markded TlN R38ES5BT!q

A Tamarack 5" in diam bears S31°W / 19.9 ft. marked TlN R38E S8BT;

A Spruce 10" in diam bears N39°E 14.8 ft. marked TlN R38ES4BT;

A Tamarack 6" in diam bears S71°E 23.8 ft.; marked TlN R38ES9BT;

All measurements are to BT; scribe along surface of ground;

USFS bearing tree signs were placed on old and new bearing trees;

I stamped the dis	ik.
	COR TIN R38E S5 S4
• · · · · · · · · · · · · · · · · · · ·	S8 S9 ORE LIC 381 1973
Office of County surveyor County State of Oregon , I hereby certify that it	the within instrument was filed in this office
for record of the	the within instrument was filed in this office; 19.7.3. , at5 o'clock
(COUNTY OFFICIAL)	PROFESSIONAL LAND SURVEYOR
	J. S. Cong

Form R6-7100-57 (9/66)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: The USGLO record of John W.	E-9
Kimbrell. U.3. Deputy Surveyor, under contract No. 579, dated June 22, 1391 states:	: DIAGRAM :
Set cost 4 ft, long, - ins. square, 24 ins. in the ground for cor. to sec.	1
4-5-8 and 9 marked "TiN S4 on NE, R28E S9 on SE, S8 on SW, and S5 on NW faces with 5 milithes on the south and 5 notches on east edges.	! TIN R38E : ! 55 S4 :
from which	
A spruce, Tips. dia. bears N. 81°W., 26 lks. marked "TIN R38E S5 BT."	1 S8 S9
A temped, 18 ins. dia. bears S. 62°W., 25 lks. marked "TIN R38E S8 BT"	!
A fig. 14 ins. dia. bears S. 23°E., 23 lks. marked TiN R38E S9 BT° A fig. 6 ins. dia. bears N. 81°E., 23 lks. marked "TiN R38E S4 BT°	i i
Pastored by J. Voelz in 1973 from the original SE and SW bearing trees per Fi	ile 38-84R.
$\delta st \approx 0^{\circ} \times 30^{\circ}$ aron pipe with brass cap stamped "COR TIN R38E S4/S5/S8/S9 ORE LIC	
from which new bearing trees :	
A 5° tamarack bears N.9°W., 2B.O ft., slope distance. A 5° tacarach bears 3.31°W, 19.9 ft., slope distance.	
A 10° spruce bears N.39°E., 14.8 ft., slope distance.	
4 6" teparack bears S.71°E., 23.8 ft., slope distance.	
Description of corner evidence found: A 2 1/2" iron pipe by Voelz in 1973, firmly ground with a 3" diameter brass cap stamped:	set, projecting 9° above the
COR	
TIN R38E	-
<u>95 54</u>	
52 59 Ore Lic 381	
" 1973 "	
from which the original bearing trees: A 20" larch snag bears S.82*20'W., 17.2 ft. with scribe marks "TIN R38E S8" v face (Pec. S.62*W., 25 lks.) A rotted 14" fir stump bears S.23*E., 16.7 ft. with a scribe mark visible on and bearing trees by Voelz in 1973: A 5" fallen larch bears N.6*30'W., 38.5 ft. with scribe marks "TINR38ESSBT" v A 5" broken larch snag bears 3.29*30'W., 20.3 ft. with a healed blaze. (Rec. A 15" porace bears N.39*E., 15.2 ft. with scribe marks visible on a partially a 10" larch bears S.73*15'E., 24.0 ft. with a healed blaze. (Rec. S.71*E., 23 Description of monument and accessories established to perpetuate the original location of this corner: The bearing trees: A 10" larch bears S.77*30'W., 53.3 ft. scribed "TINR38ESSBT" A 10" spruce bears N.26*W., 43.4 ft. scribed "TINR38ESSBT" I set a 6" steel fence post with F.S. signs 54-2 and 54-9, West, 5.0 ft. All bearing trees have a 6" red band painted around the tree and the blazed files. SER*2105 TREE, and sign 54-9, LAND SURVEYING MONUMENT, are nailed to all bear trees have a set of the trees the root crown, and distances are measured to the state of the trees of the root crown, and distances are measured to the state of the tree of the root crown, and distances are measured to the state of the tree of the root crown, and distances are measured to the state of the tree of the root crown, and distances are measured to the root of the tree of the tree of the root crown, and distances are measured to the root of the tree of the tree of the tree of the root crown, and distances are measured to the root of the tree of the root crown, and distances are measured to the root of the tree of the root crown, and distances are measured to the root of the tree of the root crown.	a badly rotted face. risible. (Rec. N.9°W., 28.0 ft. S.31°W., 19.9 ft.) r healed face. (Rec. 14.8 ft.) 8.8 ft.) face painted red. U.S.F.S. signing trees. All new bearing the lower blaze. Bearings are he root crown at the side and
Contain of the tree. Bearings and Distances were measured with a staff compass (De Contains). Vanning, S. Wescott.	cl. 20°E) and steel tape.
Office ofCounty of	
State of, I hereby certify that the within instrum	ent was filed in this office
for record on theday of, 19at	O'clocka., (signed)
by	
(COUNTY OFFICIAL) (DEPUTY)
I hereby certify that the above corner point was perpetuated as hereon	
SURVEYOR SURVEYOR	PROFESSIONAL LAND SURVEYOR
Dato Received ///14/92	listion O. Dethort

OREGON JULY 17, 1891 KRISTIAN O. DEGROOT 1841