


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. F-4

History of original corner establishment:

None



Description of corner evidence found:

A steel fencepost, unmarked, bears N 42 1/2°E 18.6 ft. from the monument established and described below. Refer to Record Survey No. 23-1964 on file in the Office of the Union County Surveyor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set from survey by subdivision of section.

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 28" in the ground, with brass cap attached, marked:

T1N R38E

From which we mark new BT's:

A 14" Grand Fir, scribed "NE 1/16 S7 BT" on a double blaze, bears S14°W 28.8 ft.

S7 + NE 1/16

A 12" White Fir, scribed "NE 1/16 S7 BT" on a double blaze, bears S77°E 35.7 ft.

PLS 1099
1980

Attached brass washer, marked "LS 1099" to lower blaze of each BT.

Placed steel fenceposts, 5 ft. S and E of monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct. 1979.

I hereby certify that the above described corner and/or accessories was established on Oct. 14, 1980.

Witness: John Curtiss

Compass Declination: 18° East

REGISTERED PROFESSIONAL LAND SURVEYOR
Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... County Surveyor County of..... Union
State of..... Oregon, I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL)

UNION COUNTY SURVEYOR
(DEPUTY)

Date Received _____
Date Filed _____
By _____
File No. 44-84R