


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. F-5

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set from survey by single proportionate measurement.

At the corner point we set a 2"x30" Galvanized Iron Pipe, 27" in the ground, with brass cap attached, marked:

T1N R38E  
N 1/16

S7 | S8  
PLS1099  
1980

From which we mark new BT's:

A 22" Spruce, scribed "N 1/16 S7 BT" on a double blaze, bears S2°W 28.0 ft.

A 10" Larch, scribed "N 1/16 S8 BT" on a double blaze, bears N50°E 37.8 ft.

Attached brass washer, marked "LS 1099" to lower blaze of each new BT.

Placed steel fenceposts 5 ft. S and W of monument with signs 54-2 and 54-4 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct. 1979.

I hereby certify that the above described corner and/or accessories was established on Oct. 14, 1980.

Compass Declination: 18° East

Witness: John Curtiss

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Gary L. Langlitz*  
**OREGON**  
JULY 22, 1977  
**GARY L. LANGLITZ**  
1099

Office of..... County Surveyor..... County of..... Union.....  
State of..... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by  
(COUNTY OFFICIAL)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 45-84R