


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. G-3

History of original corner establishment:

None.



Description of corner evidence found:

A steel fence post and location poster bears approx. S26°E 40 ft. from the monument described below.

See Record Survey No. 23-1964 as filed in the Office of Union County Surveyor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner set from survey at intersection of straight lines between opposite exterior ¼ corners of Section 7.

At the corner point, we set a 2"x30" Galvanized Iron Pipe, 26" in the ground, with brass cap attached, marked:

From which we mark new BTs:

A 7" Larch, scribed "C¼ S7 BT" on a double blaze, bears N54½°E 13.0 ft.

A 6" White Fir, scribed "C¼ S7 BT" on a double blaze bears N58½°W 10.9 ft.

Attached brass washer, marked "LS 1099" to lower blaze of each BT. Placed steel fence posts 5 ft. N and W of monument with signs 54-2 and 54-9 attached. Attached signs and painted BTs per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct., 1979.

Compass Declination: 18° East.

I hereby certify that the above described corner and/or accessories was established on October 10, 1980.

Witness: John Curtiss

T1N R38E

S 7

C ¼

PLS 1099

1980

Office of..... County Surveyor..... County of..... Union.....  
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 by.....  
 (COUNTY OFFICIAL)

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Gary L. Langlitz*

OREGON  
 JULY 22, 1977  
 GARY L. LANGLITZ  
 1099

**UNION COUNTY**  
**(D) SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 48-84R