


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None


Index File No. H-3



Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner: Corner set from survey at location determined by subdivision of section.

At the corner point, we set a 2"x30" galvanized iron pipe, 28" in the ground with brass cap attached, marked:



From which we mark new BT's:

A 14" White Fir, scribed "CS 1/16 S7 BT" on a double blaze bears N71°E 41.0 ft.,

PLS 1099
1980

A 16" Spruce, scribed "CS 1/16 S7 BT" on a double blaze bears N19°W 25.6 ft.

Attached brass washer, marked "LS 1099" to lower blaze of each BT.

Placed steel fenceposts 5 ft. E of monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, October 1979.

I hereby certify that the above described corner and/or accessories was established on October 10, 1980.

Compass Declination: 18° East

Witness: John Curtiss

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... County Surveyor..... County of..... Union.....
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
Date Filed _____
By _____
File No. 55-84R