## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

				Index Fi	le No. J-3
History of original corner establishment:		1/4	7/18	DIAGRA	u
Record of the original survey by J. Kin 1891, states:	mbrell,	TIN	R38E	TIN	R38E
A Fir, 3" diam. which I mark ¼ S of for ¼ sec. cor., from which:	on N face			(	1 <sub>4</sub>
A Fir, 3" diam. bears N20 <sup>0</sup> W 7 lks	dist. mark	ked ¼ S BT.			
A Fir, 5" diam. bears S7 <sup>0</sup> W 32 lks	dist. mark	ked ¼ S BT.			
·				L	
Description of corner evidence found: No tra	ce remains	of the ori	ginal c	orner or	accessories.
					-
• *					
portionate measurement.  At the corner point, we set a 2"x30" grown attached manked:				·	
cap attached, <u>marked</u> :					TIN R38E
From which we mark new BT's:			N=00.		S 7
A 22" Larch, scribed "¼ S 7 BT" o 84.8 ft.					S 18
And a 20" White Fir, scribed " $\frac{1}{4}$ S S53 $\frac{1}{2}$ 0W 52.3 ft.	18 BT" on	a double b	laze be	ars	PLS 1099 1980
Attached brass washers stamped "LS 109	9" to lower	blaze of	new BT'	s.	
Placed steel fencepost 5 ft. East of m	onument wit				
Attached signs and painted DTIs now St		th sign 54-	9 attac	hed.	
Attached signs and painted BT's per <u>St</u> U.S.F.S. Region 6, October 1979.		_			urvey,
U.S.F.S. Region 6, October 1979.	andard Spec	cifications certify tha d/or access	For Ca	dastral <u>S</u> bove desc as establ	ribed ished
U.S.F.S. Region 6, October 1979.  Compass Declination: 18° East	I hereby of corner and on October	cifications certify tha d/or access	For Ca t the a ories w	dastral S bove desc as establ  REGIS PROFES	ribed
U.S.F.S. Region 6, October 1979.  Compass Declination: 18° East  Office of County Surveyor	I hereby corner and on October Witness:	certify tha d/or access 9, 1980. Mike Wagon	For Ca	bove desc as establ REGIS PROFES LAND SU CARE GARY L.	ribed ished TERED SSIONAL
U.S.F.S. Region 6, October 1979.  Compass Declination: 18° East  Office of County Surveyor State of Oregon I hereby certify	I hereby of corner and on October Witness:	certify tha d/or access 9, 1980. Mike Wagon	For Ca	bove desc as establ REGIS PROFES LAND SU CARE GARY L.	ribed ished TERED SSIONAL JRVEYOR Jangliz GON 2, 1977 ANGLITZ
Office of County Surveyor  State of Oregon I hereby certify for record on the day of October 1979.	I hereby of corner and on October Witness:	cifications certify tha d/or access 9, 1980. Mike Wagon Union	For Ca	bove descas estable REGIS PROFES LAND SI GARY L.	ribed ished  TERED SSIONAL JRVEYOR  Jangliz GON 2, 1977 ANGLITZ 99
Office of County Surveyor State of Oregon , I hereby certify	I hereby of corner and on October Witness:	cifications certify tha d/or access 9, 1980. Mike Wagon Union	For Ca	bove descas estable REGIS PROFES LAND SI GARY L.	ribed ished TERED SSIONAL JRVEYOR Janaliz GON 2, 1977 ANGLITZ 99
Office of County Surveyor  State of Oregon I hereby certify for record on the day of	I hereby of corner and on October Witness:	certify tha d/or access 9, 1980. Mike Wagon	For Ca	bove desc as establ REGIS PROFES LAND SU GARY L.	ribed ished  TERED SSIONAL JRVEYOR  Jangliz GON 2, 1977 ANGLITZ 99



Land Surveying & Boundary Consulting

P.O. Box 19 Mill City, OR 97360 (503) 897-2722

# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

CAP DIAGRAM

T1N R38E

S 7

S 18

PLS 1099

1980

1/4

### History of original corner establishment:

John W. Kimbrell, 1891, Contract 579

Set: A fir, 3 ins. dia., marked 1/4 S on N face, from which:

A fir 5 ins. dia. bears S 7° W 32 lks. (21.1 ft.) dist. marked 1/4 S BT A fir 3 ins. dia. bears N 20° W 7 lks. (4.6 ft.) dist. marked 1/4 S BT

#### Langlitz, PLS 1099, 1980, CS 97-80

Found: No trace remains of the original corner or accessories.

Set: At a point determined by single proportionate measurement a  $2" \times 30"$  galvanized iron pipe, 26" in the ground, with brass cap, from which:

A 20" white fir, scribed "1/4 S 18 BT" on a double blaze bears S 53 ½° W 52.3 feet

A 22" larch, scribed "1/4 S 7 BT" on a double blaze bears N 73° W 84.8 feet

Attached brass washers stamped "LS 1099" to lower blaze of new BTs

#### Description of corner evidence found:

Monument Found:

A 2 1/2" brasscap, marked as shown, on a 2 1/2" galvanized iron pipe, in good condition, and 4" showing above the ground. Guard post with LSM East 5.2 ft.

Accessories Found:

A white fir, (record 20 in. diam.) alive/healthy, bears S 53 1/2° W, 52.3 ft., with healed double blaze. (Langlitz BT)

A tamarack, (record 22 in. diam.) dead & standing, bears N 73° W, 84.8 ft., partial scribing visible on a double blaze. (Langlitz BT)

*Note:* Looked for original corner and its accessories. Found no remains of the original corner or original BTs.

# Description of monument and accessories I established to perpetuate the original location of this corner:

Accessories Set:

A white fir, 4 ins. diam, bears N 25  $1/4^{\circ}$  E 38.5 ft. marked X BT on a double blaze with a brass washer stamped PLS 2456.

A white fir, 6 ins. diam., bears S 25  $1/4^{\circ}$  E 14.7 ft., marked X BT on a double blaze with a brass washer stamped PLS 2456.

A white fir, 11 ins. diam., bears N 68 3/4° W 55.4 ft., marked 1/4 S7 BT on a single blaze with a brass washer stamped PLS 2456.

Red paint, posts and signs added as needed.

NAD 83 (CORS 2002) Coordinates:

Geographic

State Plane

45°34'22.2511" N

N 214,583.626Meters

118°06'28.8942" W

E 2,686,668.490 Meters

Equipment: Hand compass, Var. 18° E, Nikon total station, nylon

tape, clinometer

Date: July 21, 2003

Crew: Ron Walter, Collin Edwards-Hill

See also the Record of Survey filed concurrently with this

certification.

REGISTERED PROFESSIONAL LAND SURVEYOR

all 9/15/0

OREGON July 25, 1990 Evelyn R. Kalb 2456

EXPIRES: 06/30/2005

### UNION COUNTY SURVEYOR

Date Received 16/2//63

Date Filed /6/3//63

File Number 044-2003R