CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner not established in original survey

DIAG	RAM
T1N R38E	
E1/16	\$10
·	\$15

No record of subsequent monumentation found in County Records.

Description of corner evidence found:

None


Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set a $2\frac{1}{2}$ x 30^{11} aluminum pipe with aluminum cap marked as shown 24^{11} in ground from which:

A 16" red fir bears S 12° W 21.5Ft. marked E 1/16 S 15 BT A 8" tamarack bears N 35° W 38.8Ft. marked E 1/16 S10 BT

PROFESSIONAL LAND SURVEYOR

ÖREGON JULY 13, 1973 GREGORY T. BLACKMAN 991



Used steel tape and magnetic compass with 20° declination. Distances measured to center of tree.

Office of COUNTY QUEVEYOR County of UNION State of OLEGON , I hereby certify that the within instrument was filed in thi	s office
for record on the 4 day of OCTOBER 1. 1982 HOWALD L PERLY by John Johnson	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received