

**OREGON CORNER RESTORATION FORM**

**COUNTY:** UNION    **DATE:** 7/1/2016

**CORNER DESIGNATION:** J-21, Section Corner common to Sections 11, 12, 14 and 15  
Township 1 North, Range 38 East, W.M.

**PREVIOUS RENEWALS/SURVEYS ETC:**

Originally surveyed by Odell & Grey, Contract No. 120, dated May 27, 1867. His notes state "Set post corner for sections 11, 12, 13 and 14 from which

A Fir 24" in dia. bears N80°E 17 lks

A Fir 10" in dia. bears S50°E 41 lks

A Fir 14" in dia. bears N50°W 36 lks

**MOUNUMENT AND ACCESSORIES FOUND:**

No evidence found.

**MOUNUMENT MARKING DETAIL:**

HDJ  
T1N R38E  
S11|S12  
S14|S13  
6/2016

**MOUNUMENT AND ACCESSORIES SET:**

Per Survey No. 020-2016

Set a 2½" brass cap on 1½" x 30" iron pipe projecting 9 inches above ground on north facing slope in heavy timber from which:

A 11" Fir bears N62°W, 10.5'

A 5" Fir bears N56°E, 5.5'

A 18" Fir bears S72°E, 17.0'

A 12" Fir bears S52°W 27.5'

All bearing trees are marked with a blaze facing the corner starting at the root crow and painted red with "BT" scribed in the blaze. Attached a yellow bearing tree sign to each tree.

**LOCATION AND COMMENTS:**

Bearings taken with Silva hand compass and distances measured with a steel tape to the center of the root crown.

**OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:**

N = 704712.04  
E = 8838301.50

**COMPASS DECLINATION:** 16° East

**FIRM:** HDJ Design Group  
5 N. Colville, Suite 200  
Walla Walla WA 99362

**WITNESSES:** Joseph R. Latimer  
Tim K. Bannister

UNION COUNTY  
SURVEYOR  
Date Received 7/28/16  
Date Filed 7/28/16  
By [Signature]  
File No. 029-2016R

**SURVEYORS' SEAL:**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Greg E. Flowers*

OREGON  
JUNE 30, 1997  
GREG E. FLOWERS  
02820LS

7/25/2016  
RENEWS 12/31/2017