


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 1 N R 38 E L-07



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 031-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 2 1/2x30" aluminum pipe, 28" in the ground, with 2 1/2" aluminum cap, marked as shown from which:

NEW BEARING TREES:

- A 9" White Fir bears North 47° East a dist. of 16.15 ft., marked "C1/4 S17 BT".
- A 7" Western Larch bears South 51° East a dist. of 22.10 ft., marked "C1/4 S17 BT".
- A 3" White Fir bears South 22° West a dist. of 45.60 ft., marked "C1/4 S17 BT".
- A 5" White Fir bears North 11° West a dist. of 13.35 ft., marked "C1/4 S17 BT".

Set a steel post approximately 1 ft. from the monument.


I hereby certify that the corner was perpetuated on July 19, 2018.

Witness: Kyle A. Tucker, Ryan Skeen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



UNION COUNTY
SURVEYOR

Date Received 8/15/18
Date Filed 8/15/18
Filed By *[Signature]*
File Number 032-201811

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.