


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 1 N R 38 E M-09



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 018-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At position determined by survey, I set a 5/8"x30" iron pin with 2 1/2" aluminum cap, marked as shown below, 28 inches in the ground, from which:

A 13 inch White Fir bears North 86° East, a distance of 15.25 feet, marked S1/16 S16 BT.
An 18 inch Douglar Fir bears South 36° West, a distance of 32.60 feet, marked S1/16 S17 BT.

I set a steel fencepost approximately 1 foot North of corner monument.
I hereby certify that the corner was monumented on July 9, 2014.



Renewal Date: June 30, 2015



UNION COUNTY SURVEYOR

Date Received 7/11/14

Date Filed 7/11/14

Filed By N.L.G. Quinn

File Number 022-2014 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike in the right hand side of the bearing trees. Bearings are to a washer marked OPLS 83571 set in the upper portion of the BT blaze.

M-09