


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER

ESTABLISHED:

Corner not previously established.

T 1 N R 38 E N-06



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 031-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with a 2 1/2" aluminum cap marked as shown below, 27" in the ground, from which::

NEW BEARING TREES:

A 7" White Fir bears North 35° East a dist. of 9.75 ft., marked "W1/16 S17 BT".

A 7" White Fir bears South 5° East a dist. of 8.40 ft., marked "W1/16 S20 BT".

Set a steel post approximately 1 ft. north of the monument.


I hereby certify that the corner was monumented on August 1, 2018.

Witness: Kyle A. Tucker, Ryan Skeen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Jeffrey S. Hsu
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



**UNION COUNTY
SURVEYOR**

Date Received 8/15/18
Date Filed 8/15/18
Filed By [Signature]
File Number 030-2018R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.