


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 1 N R 38 E N-08



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 018-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with 2 1/2" aluminum cap, marked as shown below, 30 inches in the ground, from which:

An 8 inch Douglas Fir bears South 37° West, a distance of 50.65 feet, marked E1/16 S20 BT.
A 10 inch White Fir bears North 41° West, a distance of 51.35 feet, marked E1/16 S17 BT.

Corner falls approximately 15 feet East of a North/South running logging road.
I set a steel fencepost approximately 1 foot North of corner monument.
I hereby certify that the corner was monumented on July 9, 2014.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T1N R38E

S 17

E 1/16 S 20

2014

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 7/11/14

Date Filed 7/11/14

Filed By N. G. Main

File Number 027-2014R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike in the right hand side of the bearing trees. Bearings are to a washer marked OPLS 83571 set in the upper portion of the BT blaze.

N-08