


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner not previously established.

T 1 N R 38 E O-08



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 030-2021

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8"x30" iron pin, 29 inches in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

**NEW BEARING OBJECTS:**

A 10" Douglas Fir bears North 84° East, a distance of 39.65 feet, marked NE 1/16 S20 BT.  
A 17" White Fir bears South 24° East, a distance of 90.55 feet, marked NE 1/16 S20 BT.

Fence corner bears Southeast, approx 46 ft. dist. Fences bears North and East.

Set a fencepost approx. 0.5 ft. North of corner monument.

I hereby certify that the corner was monumented on June 24, 2021.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2023


UNION COUNTY  
SURVEYOR

Date Received 6/24/21

Date Filed 6/24/21

Filed By [Signature]

File Number 022-2021R



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the bearings are to a brass washer marked OPLS 83571 in the BT blaze. Distances are to a 60d spike in the right side of the root crown.