


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.

T 1 N R 38 E O-10



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 018-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with 2 1/2" aluminum cap, marked as shown below, 28 inches in the ground, from which:

- A 9 inch Western Larch bears South 13° East, a distance of 37.30 feet, marked NW1/16 S21 BT.
- A 12 inch Lodgepole Pine bears South 26° West, a distance of 39.70 feet, marked NW 1/16 S21 BT.


Corner falls on North side of an East/West running logging road. An old fence line falls approximately 30 feet South of the corner, fence runs East/West.
I set a steel fencepost approximately 1 foot North of corner monument.
I hereby certify that the corner was monumented on July 8, 2014.
Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



**UNION COUNTY
SURVEYOR**

Date Received 7/11/14

Date Filed 7/11/14

Filed By [Signature]

File Number 024-2014R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike in the right hand side of the bearing trees. Bearings are to a washer marked OPLS 83571 set in the upper portion of the BT blaze.

O-10