
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T1N R38E P-10



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 018-2014

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin with 2 ½" aluminum cap, marked as shown below, 26 inches in the ground, from which:

A 10 inch Lodgepole Pine bears South 18° East, a distance of 27.15 feet, marked CW 1/16 S21 BT.


A 9 inch Lodgepole Pine bears South 72° West, a distance of 19.20 feet, marked CW 1/16 S21 BT.

I set a steel fencepost approximately 0.5 foot South of corner monument.

I hereby certify that the corner was monumented on July 8, 2014. Witness: Thomas J. Kopp

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike in the right hand side of the bearing trees. Bearings are to a washer marked OPLS 83571 set in the upper portion of the BT blaze.

UNION COUNTY SURVEYOR

P-10