
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was never established. Position was based on survey by Duane Griffith, OPLS 644, Union County Survey 033-1994.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


A 2 1/2" x 30" aluminum pipe with a 2 1/2" aluminum cap with a mound of stone.


A 20" Ponderosa Pine bears N 25E, 83.1' scribed "C 1/4 S 21 BT".

An 18" Ponderosa Pine bears S 27 W, 16.3' scribed "C 1/4 S 21 BT".

A 2" aluminum cap on a 5/8" x 30" rebar bears N82-41-11E, 14.8'; stamped "RM".

A 2" aluminum cap on a 5/8" x 30" rebar bears S82-58-32W, 15.9'; stamped "RM".






I hereby certify that the above corner point was perpetuated as hereon described on <u>APRIL 22,1997</u>

Witnesses:

Pete Elder, LSIT Doug Thomas



E:\DOC\FORM\$\CERT-REG.GRF