CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey

5-7	
DIAGRAM	_
T1N R38E	
C-N 1/16	
\$ 29	
•	

No record of subsequent monumentation found in County Records.


Description of corner evidence found:

See map of survey No. 73-80.

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set 5/8" x 30" iron pin with plastic cap marked "BGA Survey Marker", from which:

 Λ 14" fir bears S 40° W, 52.5 ft marked CN 1/16 S29 BT A 9" tamarack bears S 78° E, 25.9 ft marked CN 1/16 S29 BT



Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 17° E declination. Distance measured to center of tree.

REGISTERED PROFESSIONAL LAND SURVEYOR
Und Shift
OREGON JULY 10, 1564 DUANE I. GRIFFITH 644

Office of	County of	*************	••••	
	eby certify that the within instrument was fi			•
for record on the day of			UNION	COUNTY

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

		_
Date Received		-
Date Filed		-
<u>.</u>		

SURVEYOR

File No. 78-84 R