
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not originally established.

## T 1 N R 38 E S-12



#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 031-2014

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At a position determined by survey, I set a  $5/8" \times 30"$  iron pin with a 2 4" aluminum cap marked as shown 30" in the ground. From which:

A 5/8" x 30" iron pin bears N 9° E, a distance of 28.95 feet, with a 1  $\frac{1}{2}$ " aluminum cap marked BGB SURVEY MARKER NE RP.

A 5/8" x 30" iron pin bears S 41° E, a distance of 13.60 feet, with a 1  $\mbox{\ensuremath{\mbox{$^{\prime}$}}}$ " aluminum cap marked BGB SURVEY MARKER SE RP.

Set a steel fencepost +/- 0.5 foot North of corner monument.

I hereby certify that the corner was monumented on October 28, 2014.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

ORIFFITH & SINGLE OF STATE OF

UNION COUNTY SURVEYOR

Date Received

File Number 0 10-2014

I use a Leica GS15 RTK GPS in the establishment of the new accessories. Bearings and distances are to the center of the aluminum cap.