
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Joseph G. Gray under GLO contract No. 120 dated May 27, 1867.

Surveyor General Record states

Set 4 section corner post from which: A fir 10" diameter bears \$ 400 E 54 links A pine 18" diameter bears \$ 880 W 64 links



Retraced by Kimbrell in 1891 who set stone $18^{**} \times 10^{**} \times 8^{**}$ in place of rotted post See narrative in map of survey.

Description of corner evidence found:

None.

See map of survey No. 73-80

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set $1^{1/2}$ x 30^{11} iron pipe with brass cap marked as shown 28^{11} in ground.

Raised mound of stone.

No trees available Steel fence post 3+ ft W T1N R38E

14

S29 S28

1980
OPLS 644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 17°E declination. Distance measured to center of tree.

File No. 81-84 R

PROFESSIONAL LAND SURVEYOR
Den I shifted
OREGON JULY 10, 1964 DUANE I. GRIFFITH 644

•						UNION COUNTY
for record on	the day of	••••			Server en la server	SURVEYOR
***************************************	(COUNTY OFFICIAL)	*************	БУ	(DEPUTY)		Pate Received
Form R6-7100-57 ((9/71)	• • • • • • •		•		Pate Filed PO-798-276