


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey.



No record of subsequent monumentation found in County Records.

Description of corner evidence found:


See map of survey No. 73-80.

Description of monument and accessories I established to perpetuate the original location of this corner:

At center of section I set 1 $\frac{1}{2}$ " x 30" iron pipe with brass cap marked as shown, 27" in ground.

Raised mound of stone

Steel fence 2+ ft West



Brass washer nailed to Bt blaze. Used steel tape and magnetic compass with 17° E declination. Distance measured to center of tree.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Duane I. Griffith*

OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

Office of..... County of.....  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_  
☆ GPO—79a.27a

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 82-84 R