

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Joseph Gray and William Odell in GLO Contract No. 120, dated May 27, 1867. Surveyor General field notes state:

Set 1/4 Section cor. post in stone mound as per instructions.

In Survey Number 022-1997, Duane Griffith finds no remaining evidence of the corner.

T 1 N R 38 E V-23



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 029-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position, I set a 2 1/2" x 30" aluminum pipe, 25 inches in the ground, in a collar of stone 1 ft. diam., with a 2 1/2" aluminum cap marked as shown below, from which:

- A 5/8" iron pin bears North 38°08' East, a distance of 17.46 feet, with a 1 1/2" aluminum cap marked NERP.
- A 5/8" iron pin at the base of a railroad tie fence corner bears South 28°11' East, a distance of 15.03 feet, with a 1 1/2" aluminum cap marked SERP.
- A 5/8" iron pin in an East/West running fenceline bears South 68°10' West, a distance of 27.01 feet, with a 1 1/2" aluminum cap marked SWRP.
- A 5/8" iron pin bears North 62°20' West, a distance of 21.13 feet, with a 1 1/2" aluminum cap marked NWRP.

Corner falls approximately 15 feet North of a fence corner. Fencelines run South and West.

I hereby certify that the corner was monumented on July 1, 2013.

Witness: Daniel Inloes

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T 1 N R 38 E

1/4 S25

S 36

2013

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 7/3/13

Date Filed 7/3/13

Filed By MLG/hsu

File Number 419-2013R

I use a Leica 1200 RTK GPS unit in the establishment of the accessories. Bearings and distances are to the center of the aluminum caps. Basis of bearings is as per Survey Number 029-2013.