
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

This corner was not established in the original survey.



No record of subsequent monumentation was found in the Union County survey records. Description of corner evidence found:

None

See Map of Survey Number 022-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey I set a 2-1/2 inch by 30 inch aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which:

## Bearing objects:

A 5/8 inch rebar bears N 11° E, 6.90 feet, with aluminum cap marked "BGB N RP"
A 5/8 inch rebar bears S 11° W, 7.08 feet, with aluminum cap marked "BGB S RP"

I hereby certify that the above corner point was perpetuated as hereon described on Aug. 30, 1997.

Witnessed by: Greg Blackman Jr

Jeff Madsen



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964

644 Renewal Date July 30, 1999

Page 16

I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° east declination and the measurement was taken to the center of the aluminum cap on the rebar.

18-28-97 9-13-97 Sign Tide a For 046-1997

W 19