# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

# History of original corner establishment:

Diagram

Original corner established by the General Land Office was re-established from evidence as described in 1980 by Union County Survey No. 38-80.

T 1N R 38 E 32 | 33

#### Description of corner evidence found:

Found bearing trees established in 1980 by Survey 38-80: an 18" Douglas Fir (1980 NW BT), alive and in good condition with scribing "T1N R38E S32 BT" and brass washer marked "LS 1294" visible on a partially-healed double blaze, and a 10" Douglas Fir (1980 NE BT), now a 6' tall stump with scribing "TIN R38E S33 BT" and brass washer marked "LS 1294" visible on an unhealed double blaze.

The 1980 corner monument, a 5/8" iron rod has been removed.

### Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 5/8"X30" iron rod (concrete reinforcing rod) with yellow plastic cap attached, marked "AP&A", buried 0.4' at the corner location by measurement from the found 1980 bearing trees,

#### FROM WHICH:

-the 1980 NW bearing tree, an18" dia. Douglas Fir, previously described, bears N 63 1/2 degrees W 24.0',

-the 1980 NE bearing tree stump, a 10" dia. Douglas Fir, previously described,

bears N 49 1/2 degrees E 22.2',
-set a 5/8" iron rod (concrete reinforcing rod) with yellow plastic cap attached, marked "AP&A" bearing \$ 47 degrees W 89.4'

-set a 5/8"X30" iron rod (concrete reinforcing rod) with yellow plastic cap attached, marked "AP&A", bears \$ 18 degrees £ 47.9', Bearings by magnetic compass, declination 17 1/2 degrees East. Distances by steel tape.

Corner visited on: July 14, 1995

Record prepared on: September 13, 1995 Survey field crew: Gary Langlitz, PLS

Jim Arnott

Anderson-Perry & Assoc., Inc. P.O. Box 1107

La Grande, Oregon 97850

ANION COUNTA SURVEYOR

Date Received 9-21-95

REGISTERED **PROFESSIONAL** AND SURVEYOR

> OKE GON GARY L. LANGLITZ 1099

EXPIRES: 12-31 -96 9-21-95