


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:
Corner not previously established




DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 018-2024
DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:
At position by survey, I set a 5/8" x 30" iron pin, 28" in the ground, with a 2 1/2" aluminum cap marked as shown, from which:

EXISTING BEARING OBJECTS:
A 19" diam. Douglas Fir bears South 8° East, a dist. of 19.50 feet, marked W 1/16 S4 BT.
An 11" diam. White Fir bears North 59° West, a dist. of 52.95 feet, marked W 1/16 S33 BT.

Set steel fence post approx. 0.3 ft. West
Corner falls approx. 30 ft. North of East/West running forest road
I hereby certify that the corner was monumented on May 21st, 2024.

Witnesses: Kyle Tucker



Renewal Date: June 30, 2025

I used a steel tape and compass in the establishment of the bearing objects. I use 14° East for a declination. Bearings are to a brass washer marked OPLS 83571 in the BT blaze of the tree and distances are to a 60d spike in the right side of the root crown.

