


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:  
Corner not previously established

T 1 N R 39 E B-09



DESCRIPTION OF CORNER EVIDENCE FOUND:  
None.

SEE SURVEY NUMBER 018-2024  
DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE  
ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8" x 30" iron pin, 29" in the ground, with a 2 1/2" aluminum cap marked as shown, from which:

NEW BEARING OBJECTS:


A 5/8" x 30" iron pin bears North 62°27' East, a dist. of 20.31 feet, with 1 1/2" aluminum cap marked "BGB SURVEY MARKER"  
A 5/8" x 30" iron pin bears North 55°25' West, a dist. of 18.03 feet, with yellow plastic cap marked "BGB SURVEY MARKER"

Set steel fence post approx. 0.3 ft. East

Corner falls approx. 8 ft. South and East of fence corner to North/East/South bearing fence lines and approx. 30 ft. East of North/South running Valley View Road.

I hereby certify that the corner was monumented on May 21st, 2024.

Witnesses: Kyle Tucker



Renewal Date: June 30, 2025

I used a Leica GS18 with RTK in the establishment of the accessories. Basis of Bearing is as per Survey 018-2024. Bearings and distances are to the center of the aluminum or plastic cap.

