
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 032-1997.

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2  $\frac{1}{2}$ " x 30" aluminum pipe with 2  $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, from which:

## NEW BEARING TREES:

A 6" diameter White Fir bears N  $34^{\circ}E$ , a distance of 3.44 feet, marked C 1/4 S5 BT.

A 19" diameter Tamarack bears S 63°E, a distance of 23.02 feet, marked X BT. An 15" diameter Tamarack bears S 62°W, a distance of 24.17 feet, marked C 1/4 S5 BT.

A 6" diameter White Fir bears N 81°W, a distance of 7.17 feet, marked X BT.


Set steel fence post approximately 2 feet South of monument.


I hereby certify that the corner was monumented on October 21, 1997.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JAY 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 1998





I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.