


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner not set by original GLO Survey.

Survey number 26-70 depicts the position of this corner. No monument was specifically called as being set at this corner on that survey.

No subsequent monumentation of this corner found in the Union County monumentation records.



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found no evidence of any monument representing this corner.

See Survey Number 032-1997.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 28" in the ground, from which:

**NEW BEARING TREES:**

A 6" diameter Tamarack bears S 46°E, a distance of 27.77 feet, marked X BT.  
A 7" diameter Tamarack bears S 67°W, a distance of 68.61 feet, marked SW 1/16 S5 BT.

Set a steel fence post approximately 2 feet West of the corner monument.

I hereby certify that the corner was monumented on October 21, 1997.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Rick G. Robinson*

OREGON  
July 17, 1986  
RICK G. ROBINSON  
2219

Renewal Date December 31, 1998

BAGETT - GRIFFITH & BLACKMAN

T 1 N R 39 E

SE 1/16

+

S 5

1997

OPLS 2219

**UNION COUNTY  
SURVEYOR**

Date Received 11-4-97

Date Filed 11-4-97

Filed By *Guy T. Clark*

File Number 052-1997R

I used a magnetic compass and steel tape in the establishment of the accessories to this corner. I used a magnetic declination of 18° East. The distance to the bearing trees is to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.