


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:  
Corner not previously established.

T 1 N R 39 E F-07



DESCRIPTION OF CORNER EVIDENCE FOUND:  
None.

See Survey Number 032-2012

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin, 20 inches in the ground, in a mound of stone 2 ft. diam., from which:

- A 5/8" x 15" iron pin bears South 42°58' East, a distance of 15.86 feet, with 1 1/2" aluminum cap marked SERP.
- A 5/8" x 15" iron pin bears South 61°16' West, a distance of 13.09 feet, with 1 1/2" aluminum cap marked SWRP.

I set a steel fence post 1 foot East of the corner monument. Corner falls on the top of a ridge, approximately 120 feet West of the break. Ridgeline runs NW and SE.

I hereby certify that the corner was monumented on October 5, 2012.


Witness: Rick Robinson

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFERY S. HSU  
83571

Renewal Date: June 30, 2013



**UNION COUNTY  
SURVEYOR**

Date Received 10/11/12

Date Filed 10/11/12

Filed By R. ROBINSON, DEPUTY

File Number 055-2012R

Bearings and distances to the reference monuments are established by a Leica 1200 RTK GPS. Distances are to the center of the aluminum cap. Basis of Bearings is as per Survey Number 032-2012.