
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by David Krumbein in 2006. Union County Minor Land Partition 20060017T states:

Set 5/8" x 30" iron rebar, w/ alum. cap PLS 933



#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None

A position determined by survey falls approx. 2 ft. North and 5 ft. East of a fence corner, remnants of which bears South and East

SEE SURVEY NUMBER 036-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown, from which:

#### **NEW BEARING OBJECTS:**

A 5/8" x 30" iron pin bears North 89°55' East a dist. of 50.50 ft., with 1 1/2" aluminum cap marked BGB SURVEY MARKER E RP.

A 5/8" x 30" iron pin bears North 0°24' East a dist. of 50.00 ft., with 1 1/2" aluminum cap marked BGB SURVEY MARKER N RP.

Set steel fence post approx. 0.3 feet North

I hereby certify that the corner was monumented on August 11, 2021.

Witness: Kyle A. Tucker

GRIFFITH & STAND STAND SERVICE SERVICE

PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

UNION COUNTY
SURVEYOR

Date Received 8/18/2)

Date Filed By Mallum SCAV

File Number 030-7021

I used a Leica GS18 in the establishment of the new accessories. Basis of Bearing ia as per Survey 036-2021. The distances and bearings are to the center of the aluminum caps.