
CFRTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T1N R39 E G-08



Description of corner evidence found: None.

See Survey Number 032-2012

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position determined by survey, I set a 5/8" x 30" iron pin, 26 inches in the ground, in a mound of stone 2 ft. diam., from which:

A $5/8" \times 30"$ iron pin bears South 41°47' West, a distance of 10.25 feet, with 1 ½" aluminum cap marked SWRP.

A $5/8" \times 30"$ iron pin bears North 41°27' West, a distance of 8.26 feet, with 1 42" aluminum cap marked NWRP.

I set a steel fencepost 1 foot North of the corner. Corner falls on the top of a ridgeline, ridge runs NW and SE.

I hereby certify that the corner was monumented on October 5, 2012.

Witness: Rick Robinson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFERY S. HSU
83571

Renewal Date: June 30, 2013

GRIFFITH & SLACE SLACE STATE S

Bearings and distances to the reference monuments are established by a Leica 1200 RTK GPS. Distances are to the center of the aluminum cap. Basis of Bearings is as per Survey Number 032-2012.