UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: None

No record of further monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 025-1998 Description of monument and accessories I established to perpetuate the original location of this corner: At the position determined by the survey I set a 2 1/2" x 30" aluminum pipe with cap 27 inches in the ground, from which:

T 1 N R 39 E M-03

NEW BEARING OBJECTS AND TREES:

An 18 inch Dia. Douglas Fir bears N 55° E, a distance of 33.12 feet, marked CS 1/16 S18 BT

An 11 inch Dia. Douglas Fir bears S 79° W, a distance of 6.98 feet, marked CS 1/16 S18 BT

I hereby certify that the corner was monumented on July 30, 1998. Witness: Jeff Madsen, Greg Engelgau, and Norb Volny.


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON

RICK G. ROBINSON

2219

Renewal Date December 31, 1998



OPLS 2219

UNION COUNTY SURVEYOR

Data Danainad

8/10/98

Date Filed _

8/19/98

Filed By

File Number _____

023-1998R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d nail driven into the root crown of the bearing tree on the right side. I attached a brass washer marked OPLS 2219 to the BT blaze.