UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None

No record of further monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 025-1998 Description of monument and accessories I established to perpetuate the original location of this corner: At the position determined by the survey I set a 2 1/2" x 30" aluminum pipe with cap 28 inches in the ground, from which:

T 1 N R 39 E M-06

NEW BEARING OBJECTS AND TREES:

A 20 inch Dia. Douglas Fir bears N 14° E, a distance of 7.35 feet, marked SW 1/16 S17 BT

A 12 inch Dia. Douglas Fir bears N 73 $^{\circ}$ E, a distance of 96.66 feet, marked SW 1/16 S17 X BT

I hereby certify that the corner was monumented on July 31, 1998. Witness: Jeff Madsen, Greg Engelgau, and Norb Volny.


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON

RICK G. ROBINSON

2219

Renewal Date December 31, 1998



UNION COUNTY SURVEYOR

Date Received ___

8/10/98

Date Filed

8/29/98

Tiled De

File Number <u>025-1998</u>/R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination. Distances are to a 60d spike driven into the root crown of the bearing tree in the right side. A brass washer marked OPLS 2219 was attached to the BT blaze.