UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.


No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004 Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" aluminum cap, marked as shown, 20 inches in the ground from which:

T1N R39E O-10



NEW BEARING TREES:

A 10 inch diameter Douglas Fir bears N 10 $^{\circ}$ E, a distance of 59.74 feet, marked NW 1/16 S21 BT

A 14 inch diameter Ponderosa Pine bears N 48° W, a distance of 26.31 feet, marked NW 1/16 S21 BT $\dot{}$

Raised mound of stone around monument, 2 ft. base to top of cap.

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 13, 2004.


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON

2219

Renewal Date December 31, 2004



Date Filed By File Number 049-2004 R

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 18° East magnetic declination and the distances are to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.