UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE


See Survey Number 033-2004

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" aluminum cap, marked as shown, 28 inches in the ground from which:

T1N R39E P-10



NEW BEARING TREES:

A 10 inch diameter Douglas Fir bears S $10\,^{\circ}$ E, a distance of 6.76 feet, marked CW1/16 S21 BT

An 11 inch diameter Douglas Fir bears N $27\,^{\circ}$ W, a distance of 30.86 feet, marked X BT

Set steel fence post approximately 1 ft. North of corner monument.


I hereby certify that the corner was monumented on October 29, 2004.

Witnesses: Greg Blackman, Jr. and Rick Thew

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 2004



UNION COUNTY
SURVEYOR

Date Received #15/04

Date Filed By #15/04

File Number 051-2004R

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 18° East magnetic declination and the distance is to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.