UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.


No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004 DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER: At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" aluminum cap, marked as shown, 26 inches in the ground from which:

T1N R39E Q-10



NEW BEARING TREES:

A 12 inch diameter Tamarack bears S 49 $^{\circ}$ W, a distance of 23.44 feet, marked SW 1/16 S21 BT

A 7 inch diameter Tamarack bears N $27\,^{\circ}$ W, a distance of 25.25 feet, marked X BT

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 22, 2004.

Witness: Greg Blackman, Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON 2219

Renewal Date December 31, 2004



UNION COUNTY SURVEYOR

Date Received 1/15/0

Date Filed

Filed By

I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 18° East magnetic declination and the distance is to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.