UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.


No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004 Description of Monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 5/8" x 30" iron pin with 2 ½" aluminum cap, marked as shown, 26 inches in the ground from which:

T1N R39EQ-11



NEW BEARING TREES:

A 10 inch diameter Douglas Fir bears S $75\,^{\circ}$ W, a distance of 33.10 feet, marked CS 1/16 S21 BT

A 6 inch diameter Ponderosa Pine bears N 56° W, a distance of 20.30 feet, marked X BT

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on November 9, 2004.

Witnesses: Greg Blackman, Jr. and Rick Thew


REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

RICK G. ROBINSON

2219

Renewal Date December 31, 2004



UNION COUNTY SURVEYOR

Date Received _

Date Filed

Filed By

116/04

I used a steel tape and magnetic compass in the establishment of the new bearing trees. I used 18° East magnetic declination and the distance is to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.

Q-11