

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 033-2004

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown, 27 inches in the ground from which:

NEW BEARING TREES:


A 15 inch diameter Ponderosa Pine bears S 41° W, a distance of 33.09 feet, marked E 1/16 S28 BT

A 14 inch diameter Ponderosa Pine bears N 73° W, a distance of 76.18 feet, marked E 1/16 S21 BT

Set steel fence post approximately 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 19, 2004.

T 1 N R 39 E R-12




REGISTERED PROFESSIONAL LAND SURVEYOR

Rick G. Robinson

OREGON July 17, 1986 RICK G. ROBINSON 2219

Renewal Date December 31, 2004



I used a steel tape and magnetic compass in the establishment of the bearing trees. I used 18° East magnetic declination and the distance is to a 50d nail set in the right side of the root crown. I set a brass washer marked OPLS 2219 on the BT blaze.

UNION COUNTY SURVEYOR

Date Received 11/15/04
Date Filed ~~11/15/04~~ 11/16/04
Filed By *[Signature]*
File Number 061-2004 R