CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Timothy Davenport in GLO Contract No. 102, dated July 20, 1863. Surveyor General field notes state:

Set post gr. Sec. corner in the West side of ascending ridge and made mound of rock.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.



See Survey Number 029-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportionate position, I set a 2 1/2" x 30" aluminum pipe, 25 inches in the ground, with a 2 $\frac{1}{2}$ " aluminum cap marked as shown below, in a mound of stone, 3 ft. diam., from which:

- A 5/8" iron pin bears North 53°09' East, a distance of 20.09 feet, with a 1 ½" aluminum cap marked NERP.
- A 5/8" iron pin in an East/West running fenceline bears South 55°59' East, a distance of 17.12 feet, with a 1 ½" aluminum cap marked SERP.
- A 5/8" iron pin in an East/West running fenceline bears South 31°54' West, a distance of 10.64 feet, with a 1 ½" aluminum cap marked SWRP.
- A 5/8" iron pin bears North 47°07' West, a distance of 21.48 feet, with a 1 ½" aluminum cap marked NWRP.

Corner falls approximately 10 feet North of an East/West running fenceline. I set a steel fencepost approximately 1 foot North of the corner monument.

I hereby certify that the corner was monumented on July 1, 2013.

Witness: Daniel Inloes

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON June 2, 2010 JEFFREY S. HSU

83571

Renewal Date: June 30, 2015

GRIFFITH **R38E R39E** 1/4 S 30 2013 **OPLS 83571**

UNION COUNTY **SURVEYOR** 423-2013R

I use a Leica 1200 RTK GPS unit in the establishment of the accessories. Bearings and distances are to the center of the aluminum caps. Basis of bearings is as per Survey Number 029-2013.