


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 1 N R 39 E X-12



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 011-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 29 inches in the ground, with 2 1/2" aluminum cap marked as shown, from which:

NEW BEARING OBJECTS:

A 10" Ponderosa Pine bears South 76° West, a distance of 94.10 feet, marked CE1/16 S33 BT.
A 12" Ponderosa Pine bears North 22° West, a distance of 123.65 feet, marked CE1/16 S33 BT.

Falls approx. 50' South and 30' West of fence corner of South and East running barb wire fences.

I hereby certify that this monument was set April 12, 2018. Set a steel fencepost approx. 1 ft. North of corner monument.

Witness: Kyle Tucker

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019


**UNION COUNTY
SURVEYOR**

Date Received 4/25/18

Date Filed 4/25/18

Filed By [Signature]

File Number 011-2018R



I use a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Distances are to a spike in the root crown of the trees. Bearings are to a brass washer in the lower blaze marked OPLS 83571.