

UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by William H. Odell under GLO contract Number 120, dated May 27, 1867. Surveyor General record states:

Set 1/4 Sec post Cor drove charred stake and raised mound as per instructions.

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey #043-1999

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At fence corner I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 27" in the ground from which:

A 5/8" x 30" rebar with aluminum cap bears N48°E, a distance of 12.86 feet, marked "UNION COUNTY SURVEYOR NE RP".


A 5/8" x 30" rebar with aluminum cap bears S2°W, a distance of 22.73 feet, marked "UNION COUNTY SURVEYOR SE RP".

A 5/8" x 30" rebar with aluminum cap bears S49°W, a distance of 7.40 feet, marked "UNION COUNTY SURVEYOR SW RP".

A 5/8" x 30" rebar with aluminum cap bears N85°W, a distance of 9.87 feet, marked "UNION COUNTY SURVEYOR NW RP".

I hereby certify that the corner was monumented on November 29, 1999.
Witness: Norbert W. Volny, Gregory T. Blackman Jr.


T 1 N R 40 E C - 09



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gregory T. Blackman
OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Renewal Date: Dec. 31, 1999



UNION COUNTY SURVEYOR

Date Received 12/13/99

Date Filed 1-7-2000

Filed By R. ROBINSON DEARY

File Number 057-1999R

I used a total station with the same basis of bearings as Survey #023-1998 in the establishment of the new accessories. The distances are to the center of the aluminum cap.