

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**


None

No record of subsequent monumentation found in UNION COUNTY survey records.

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None

See Survey Number 035-2000.



**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin with 2" aluminum cap marked as shown below, 27" in the ground.

**NEW BEARING TREES:**

A 12" Diameter Western Larch bears S81°W, 7.87 feet, marked NE1/16 S13 BT.

An 8" Diameter Douglas Fir bears N43°E, 19.04 feet, marked NE 1/16 S13 BT.

Set steel fence post approximately 1 ft. South of corner monument.

I hereby certify that the corner was monumented on November 15, 2000.


Witnesses: Norbert Volny and Greg Blackman Jr.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Rick G. Robinson*

OREGON  
July 17, 1988  
RICK G. ROBINSON  
2219

Renewal Date December 31, 2000



UNION COUNTY  
SURVEYOR

Date Received 11/22/00

Date Filed 12/27/00

Filed By *Greg T. Oke* ✓

File Number 033-2000R

I used a total station instrument in the establishment of the new accessories. I used the same basis of bearing as survey number 035-2000, the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the bearing tree blaze.